
SEPARATION OF MOLDING (SEAMS) ALONG FRONT LEFT AND RIGHT SIDES OF ROOF.
MOLDING SEPARATING AROUND WINDOW
BOWING AND SEPARATION OF EXTERIOR SIDING IN THE AREA AROUND FRONT WINDOW IN THE AREA SHADED YELLOW.
BOWING OF INTERIOR FRONT COMPARTMENT FLOOR
FRONT LOWER STORAGE COMPARTMENT DOORS MAY BIND AGAINST THE FRAME MAKING THE COMPARTMENT DOOR DIFFICULT TO OPEN.
BOWING OR SEPARATION OF EXTERIOR SIDING IN THE LOWER FRONT SECTION.
BOWING OR SEPARATION OF THE PANEL LOCATED ON THE FORWARD BED SUPPORT.
CRACKED EXTERIOR FIBERGLASS SIDING OR CREASED METAL EXTERIOR SIDING LOCATED IN FRONT OF THE LOWER FRONT STORAGE COMPARTMENTS.